AGMPM – Quality & Lean Card Nr 3
What ?: Lean Model (Design)

Eco6s
Statistical Analysis
Environmental Analysis
Technical Analysis

„ Use Metric and not Mystic“ Archimedes: Ἀρχιμήδης

WHAT	The Lean Model is designed to analyze present Values and deduct future Values. A Model is a scientific functional Equation: Y = f(X) where X are INPUTS (Costs) and Y are OUTPUTS (Quality requiered)
WHY	Analyzing present Y-Values (**T**oxical Values & **S**ustainable Values), will identify X-Causes (**E**nergy Costs, **M**aterials Costs, **P**rocess Costs) causing Functions or Dysfunctions of the System and deduct the Lean 8 RE-Actions to reduce Costs to get Sustainable Values Quality is devaluated when Cost is increasing  Too much Costs for a poor Quality
HOW	The T.E.M.P.S. Method is used to find the Equation of the System and detect the 8 Lean Reactions to Reduce X-Costs of **E**nergy, **M**aterial & **P**rocess to create Y-**S**ustainable Values and Y-non **T**oxic Values. The Eco6s TEMPS Equation to reduce Costs and create Values Get the Best Y in reducing X Costs  REDUCE Weight To create Value
WHO	Quality & Industrial Teams to analyze Y-OUPUTS (Sustainable Values) R&D Teams to innovate with the 8 Sustainable RE Actions of X-INPUTS. Management Teams to define Y-Sustainable and non Toxic Values.
WHEN	Lean Model & Design to be planned with Specifications Proceedings.

gerald.lefebvre@t-online.de